



NGS 3H/5H version 9.0.1.8 Software update content description

Applicable models

NGS 5H

NGS 3H

Available Firmware Version

9.0.1.7

Attention

The system will reboot twice after upgrading the new version. It may take around 3 to 5 minutes.

Update

※ Wizard ※

(1) ADD : Network Interface Setting-LAN > DHCP Gateway Setting.

※ Object ※

Application Control →

MODIFY : an issue that after upgrading firmware, the authorization of application control and URL filtering would be invalid.

※ URL Filter ※

(1) MODIFY : URL an issue that URL filtering did not work.