



## HiGuard Pro+ 2.2.1.5 Firmware Update

### Available Firmware Version

2.2.1.4 (467dc47fdce8937752ff793c75a2fdb27ef9c61c)

### NOTES

1.  
The system will reboot twice automatically after upgrading to the new version. (It may take 3-5 minutes)
2.  
The system upgrade requires about 15 MB of disk space. If there is not enough free space on your device, the update will be paused.

### Update Items

---

#### ※Policy → WAN Policy※

FIX popup error messages while opening 【Realtime Traffic】 .

#### ※Object → Bulletin Board※

Enhance file uploading security level.

#### ※Others※

- (01) 【Admin Interface】 ADD “TIPS” to show the hotfix version on the main page.
- (02) 【System】 ENHANCE the system security to prevent all types of vulnerability risks.
- (03) 【Admin Interface】 FIX an issue that users cannot use HTTPS to connect due to outdated TLS versions.

2022/07