

NTS version 5.2.0.2 firmware update

Available Model

NTS 1134-F/NTS 1136F/NTS 1154FR/NTS 3356FR/NTS 3372FR

Available firmware version

5.2.0.1

Attention

1 The system will be rebooted in 35

minutes after upgraded the new version.

2 If the version is not 5.2.0.x, the system will be rebooted without update process.

Upgraded items:

=====

Add:

-Add model NWA1100-NH, NWA5123-AC, WAC6103D-I at Configuration > AP management.

-Add new applicable program for Kaspersky at Network Services > Anti-Virus Engine > Kaspersky.

-Add enabling management service which are Ping, HTTP, HTTPS at LAN and DMZ.

Modify:

-Modify Flow Direction which can't display WAN 4 to WAN 6 at Status > Top N Flow and Top N Search.

-Modify the issue which can't search logs after edited Policy > LAN Policy > LAN to WAN.